## **Under Review Notification**

Raised By: Vanessa Morel Product #: RBT18651

Date: 2019.10.29 Product Name: ENGINE INLET DUST PLUG

		"Y" or "N" Required for Each Part Do not leave blank							t		
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers		Quarantine Tooling (Jigs, Fixtures, etc.)	¥	IPP Under Review (Enginer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")	Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
RBT18651	RBT18651 Rev	Υ	Υ	N	Υ	Υ	N	N	N	19-1076	See below

## Description of Issue:

Issues stated on ADR (Manufacturing issues)

RBT18651 and item -1 must be put on HOLD in Plex

RBT18651 Finish good stock can be use as is

Item -1 stock must be put in quarantine

No new manufacturing is permitted until Engineering release new Rev

Can remain on website with a note to contact sales for a quote. They must NOT be able to put the tool into cart

'P" Part must be put on HOLD in Plex as well

Distribution: **VP Operations** Director of Engineering Customer Support Manager **Technical Support** 

**Director of Operations** Chief Engineer **Production Engineers** 

Product Manager - Solutions Provider Director Quality Assurance **Engineering Project Managers Production Planners** Supply Chain Director / Senior Buyer

**Engineering Clerk Purchasing Manager** Marketing Eugene QC Coordinator